

## Step III - Choose Your Color (Please refer to color chart)

400 - Solid Color Finishes and Washes

600 - Multi-Color Finishes

## Step IV - Choose Your Accents Add Copper or Stainless Steel Bands

### Copper Metal Bands

### Stainless Steel Metal Bands

Raw copper will turn bronze in a dry climate and may patina in a wet climate

Placement	Raw Copper Code	or	Brushed & Sealed Copper Code	Placement	Unbrushed SS Code	or	Brushed SS Code
Top Metal Band	775		778	Top Metal Bands	781		784



Bottom Metal Band	776		779	Bottom Metal Bands	782		785
-------------------	-----	--	-----	--------------------	-----	--	-----



Middle Metal Band	777		780	Middle Metal Band	783		786
-------------------	-----	--	-----	-------------------	-----	--	-----



Placement	Raw Copper Code	or	Brushed & Sealed Copper Code	Placement	Unbrushed SS Code	or	Brushed SS Code
Top and Bottom Metal Band	850		851	Top and Bottom Metal Bands	852		853

